290 W. Palmetto Park Road #314

Boca Raton, FL 33432

954-895-4633

www.performancemarinesurveyors.com

High Performance Specialist

SURVEY, CONDITION AND INSPECTION REPORT

This survey reports the condition of the vessel including hull, machinery equipment, fittings and outfit to the best of our knowledge without removing the paneling, ceiling, bulkheads or other parts of her structure and without internal examination of engines and machinery. This report represents our true and unbiased opinion of the Survey but in no event is this report to be considered a guarantee. Neither this office nor the undersigned Surveyor shall be liable in damages of any nature whatsoever for any errors of judgment, omissions or mistakes in making this survey and report.

SPECIFIC INFORMATION

Survey No. PMS-041928

NAME OF VESSEL TYPE NUMBER BUILDER WHERE BUILT YEAR BUILT <u>2014</u> L.O.A. <u>34' 5"</u> NET WT. <u>10,000</u> #	L.W.L	HAULED	DATE SURVEYED F ADDRESS CITY, STATE SURVEYED A Yes 10' DRA NSTRUCTION	4T _ UNI	DERWATER SURV 30" CLEARAN led and cored fiberg		<u>No</u>
		MAIN ENG	INES				
MODEL T- 300 Me	rcury Verado 4-stroke	TYPE	Outboard	COOLIN	G Raw water	H.P.	300
ENGINE SERIAL NUM	IBERS: P- 2B033098 -	- 332 hrs. S-	2B032208 - 3	332 hrs.	C	YL	6
TRANSMISSION	- REDU		- SHAFT	SS	PROPELLER	21" 4 bla	de SS
	ELEC		QUIPMENT				
SHIP TO SHORE	Garmin 100 VHF		DEPTHOME	TER	Garmin GPSmap 4	212	
AUTO PILOT	-	RADAR		-			
GPS	Garmin GPSmap 4212	Garmin GPSmap 4212			Audiopipe stereo w/Jensen amps		
	AUX	(ILIARY EQ	UIPMENT				
BILGE PUMP	2-2000 GPH Rule with a	auto & alarm	GENERATO	R	-		
WATER HEATER -			REFRIGERATOR		-		
AIR CONDITIONER	-		STOVE				
	ANCI		ORMATION				
PURPOSE OF VESSE	L Pleasure	• \	WATERS NAV	IGATED	Coastal & Nearb	y Islands	
EXPERIENCE OF SKI	PPER OR OWNER	UN	IK	CR		1	
REPLACEMENT \$	400,150 BOAT VALUI	VALUATI(E \$195,350		INCL	PRES. VALU	JE \$195	5,350

Page 2 of 7

Survey No. PMS-041928

ITEM	MINT	GOOD	FAIR	POOR	COMMENTS
воттом	x				White gelcoat – finish bright – no damage
TRIM TABS	х				Lenco dual-ram with LED indicators & auto retract feature – operate properly
STRUTS & RUDDERS					-
PROPELLERS	x				21" P Mercury Revolution 4 - finish bright
LOWER UNITS	х				New condition
TOPSIDES	x				Seafoam green Imron with clear coat – finish bright – new condition
SUPERSTRUCTURE	х				Center console with hardtop – new condition
СОСКРІТ	x				Sea Deck sole – new condition
EXT. UPHOLSTERY	x				Brown & green vinyl – no damage – clean
CANVAS					-
DECKS	х				White gelcoat non-skid– no damage
CHOCKS & CLEATS	х				Ample size and amount – pop-up cleats
DECK RAILINGS	х				Welded aluminum - secure
SPARS					-
ANCHOR WINDLASS	x				Lewmar – operates properly
RUNNING RIGGING					-
COMPASS					-
GAUGES	x				Displayed in Garmin unit

PERFORMANCE MARINE SURVEYORS, INC. Survey No. PMS-041928

Page 3 of 7

ITEM	MINT	GOOD	FAIR	POOR	COMMENTS
GROUND TACKLE	х				Bow mounted polished plow anchor with ample chain rode and Lewmar electric windlass
FIRE EXTINGUISHERS		х			2 – BC size 1 dry chemical fire extinguishers – properly mounted and show fully charged
SAFETY GEAR		х			12 Type II & 1 Type IV PFDs - ignition kill switch, horn See Rec. #1
FUEL TANKS	Х				257-gallon aluminum approved tank – no leaks evident
FUEL LINE & VALVES	Х				Approved type – no leaks evident
WATER TANK & PLUMBING	Х				40-gallon aluminum approved tank - secure – no leaks sighted
SANITATION SYSTEM			Х		Dometic Vacu-flush system – operates properly – 20-gallon plastic holding tank See Rec. #2
BATTERIES	Х				3 group 27 batteries w/isolator – secure
D/C ELECTRICAL	х				12 volt on breakers – wiring secure
ELECTRONICS	Х				Excellent units – power-up properly
NAVIGATION LIGHTS	Х				Meet all USCG requirements – all working
A/C ELECTRICAL	х				120-volt 15-amp – polarity correct – GFI protected
A/C AUXILIARY EQUIPMENT	х				Battery charger only
GALLEY APPLIANCES					-
ENGINE COMPARTMENT					-
VENTILATION					-
BILGES	х				Clean & free of dirt and debris
BILGE PUMPS	х				Operate properly – new appearance

Page 4 of 7

Survey No. PMS-041928

ITEM	MINT	GOOD	FAIR	POOR	COMMENTS
STEERING	Х				Mercury Verado hydraulic with power assist and tilt helm
RUDDER LOGS AND PACKING					-
SHAFT LOGS & PACKING					-
ENGINES	х				2- Mercury 300 Verado SC 6 cylinder – 332 hours – custom painted cowlings
TRANSMISSIONS					-
EXHAUST SYSTEM					-
AUXILIARY GENERATOR					-
ENGINE BED & MOUNTS	х				Secure to transom well
THRU-HULL FITTINGS	Х				Approved type – no leaks
SEACOCKS	Х				Approved type – no leaks
RAW WATER HOSES & CLAMPS	х				Approved type – no wear noted
BULKHEADS	х				No evidence of failure where sighted
STRINGERS & FRAMES	х				No evidence of failure where sighted
COCKPIT & DECK BEAMS	х				No evidence of failure where sighted
FASTENINGS	х				Premium grade marine stainless steel – secure
CABIN					-
TRAILER					-
STATEROOMS					-

TRIAL RUN

Port Engine 332 hrs.

Starboard Engine 332 hrs.

	RPM	WATER TEMP.	OIL PRES.	VOLTS		RPM	WATER TEMP.	OIL PRES.	VOLTS
SLOW	600	141	52	13.8	SLOW	600	140	52	13.7
HALF	3000	144	55	13.8	HALF	3000	145	56	13.8
CRUISE	3200	150	56	14.2	CRUISE	3200	152	58	14.3
FULL	6000	155	58	14.3	FULL	6000	156	58	14.3

PERFORMANCE

Trial Run performed with 2 adults in open, choppy waters with 1/2 fuel. Engines started quickly with no excessive cranking and idled and shifted smoothly. Boat planed quickly and accelerated smoothly to top RPMs without straining. Helm and trim tabs responded properly.

REMARKS

- 1. All gauge readings were within acceptable parameters.
- 2. Performance was very good.
- 3. Cooling system water has good volume and pressure.
- 4. Steering was excellent with no negative feedback.

Page 6 of 7

Edward Cozzi performed this survey on April 26, 2019 in Pompano Beach, Florida.

RECOMMENDATIONS

* Pertains to safety or does not comply with USCG, NFPA or ABYC regulations

- 1.* Equip vessel with an approved distress kit including current flares.
- 2. Strong odor from sanitation system. Investigate and remedy situation.

EXTRAS & EQUIPMENT

Including but not limited to:

- 1. Welded aluminum forward grab rails
- 2. Windline stainless steel boarding ladder
- 3. Lenco electric trim tabs with LED indicators & auto retract feature
- 4. Mercury Verado hydraulic steering with power assist & tilt helm
- 5. Fiberglass hard-top with electronics box
- 6. LED spreader lights
- 7. Lewmar electric anchor windlass
- 8. Sea Deck cockpit & deck sole
- 9. Garmin GPSmap 4212 GPS
- 10. Mercury SmartCraft DTS control & gauges
- 11. Audiopipe deluxe CD stereo system w/Jensen amps
- 12. Garmin 100 VHF
- 13. Pop-up cleats
- 14. Ignition kill switch
- 15. ProMariner 30-amp battery charger
- 16. Transom door & shower
- 17. Bow mounted polished plow anchor
- 18. Dometic electric-flush sanitation system
- 19. 3 group 31 batteries with isolator
- 20. Gunwale rod storage
- 21. 2 2000 & 1 750 GPH Rule bilge pumps with auto switches & high-water alarm
- 22. 2 BC size 1 dry chemical fire extinguishers
- 23. 120-volt 15-amp shore power
- 24. Live baitwell
- 25. 21" Revolution 4 stainless steel 4-blade propellers
- 26. Underwater lights
- 27. Fresh and raw water wash downs
- 28. Fishboxes w/macerators
- 29. 10 Type II & 1 Type IV PFDs
- 30. AFI electric horn

Page 7 of 7

Survey No. PMS-041928

IDENTIFICATION

This craft is a 2014 35' Statement Center Console Open built by Statement Powerboats, LLC in St. Petersburg, Florida. Power is provided by twin Mercury Verado 300 HP outboard engines turning 21" P 4 blade stainless steel propellers. The hull number is STTFB029L314 and there is no common name.

NARRATIVE

This vessel is laid-up in white gelcoat. The upholstery is white with beige and green trim. The Ttop frame and bow rails are power coated welded aluminum. The topsides are painted seafoam green. The cockpit and deck soles are gray Sea Deck.

Center is a large console with a door facing forward that accesses the bathroom. The console with helm is centered with two leaning post/seats with drop-downs. A transom door and shower are aft. The outboard engines are through-bolted to the transom.

GENERAL COMMENTS

This craft is in excellent condition overall. The finish is bright and glossy, and the engines are clean and in pristine condition. I found no sign of damage, abuse or neglect anywhere on this vessel.

This vessel was inspected with a FLIR MR-176 thermal imaging camera and found to be free of trapped moisture in the laminates or coring.

This survey is based on the facts presented and discovered and does not constitute a certificate of seaworthiness nor a warranty of the vessel, either implied or expressed. No structural or engineering analysis of the hull structure or any system was made. The scope of this survey is for buyers' pre-purchase valuation and to discover any defective conditions without destructive removals to expose concealed parts.

Signed Without Prejudice: Performance Marine Surveyors, Inc.

By: By:

Edward R. Cozzi, President, PMS, ABYC For the Corporation ERC/ec