

# Dependable Home Inspections

## \*\*\* Residential Inspection Report \*\*\*



### Client's Name

[REDACTED]

### On

March 13, 2019

### Inspection Address

[REDACTED]

Gridley, Ca 95948

### Inspected By

Jason K Gonzales

530-762-8981

14695 Bridgeport Circle, Magalia, Ca 95954

DependableHomeInspectionsCa@gmail.com

www.DependableHomeInspectionsCa.com

## Inspection Report Directory

<b>Inspected locations</b>	<b>Page #</b>
Cover Page	1
Index	2
Client Information	3
Summary	5
Utilities	6
Grounds	9
Structural Systems	12
Roof & Attic	16
Fireplace & Chimney	19
Interior	22
Bedroom	24
Laundry	25
Bathroom(s)	27
Kitchen	29
Kitchen Appliances	31
Heating and Cooling	34
Water Heater	36
Pool Spa	37

## Dependable Home Inspections

Date Of Inspection: March 13, 2019  
Inspection Address: [REDACTED], Gridley, Ca 95948

### General Information

#### Client Information

Name: [REDACTED]  
Street Address: [REDACTED]  
City, State, Zip: [REDACTED]  
Phone #: 530-539-0479  
Email Address: [REDACTED]

#### Inspection Address

Street Address: 670 Colusa Highway  
City, State, Zip: Gridley, Ca 95948

#### Weather Conditions

Weather Type: Clear  
Temperature: 46 Degrees

#### Structure Type

Single Family / Two Story

#### Construction Type

Stucco with wood frame construction

#### Number of Bedroom/Bath

4 Bedroom / 3 Bath / 3 Car Garage

#### Estimated Year Built

1980

#### Estimated sq. ft.

2,438

#### Time of Inspection

10:45 AM

#### Inspected by

Jason K Gonzales

#### Buyer Agent

Name: Joie Altstatt  
Phone #: (209) 985-7659  
Email Address: joiealtstatt@yahoo.com

#### Listing Agent

Name:  
Phone #:  
Email Address:



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED], Gridley, Ca 95948

---

### Inspection / Report limitations

This report is the exclusive property of inspection company and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited. The observations and opinions expressed within this report are those of inspection company and supersede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with home inspector's standards of practice. The report is not intended for third party dissemination. This report shall not be forwarded to any other person, company, or legal entity without inspection company express written approval. Inspection company copyrights this report, which is protected by copyright law.

This inspection report is to inform you of current condition as observed at time of inspection. As a general rule cosmetic deficiencies are considered normal wear and tear and are not within the scope of this inspection unless they constitute major and visually observable defects as defined in the Inspection Agreement. However some items, which may be considered cosmetic in nature, may have been noted to assist you in evaluating other issues covered in the Inspection Agreement.

It is ultimately your decision on what concerns you would like corrected. Keep in mind that if you do not get them corrected now the defects will have to be corrected in the future at your expense. It is not possible to detect every concern during a general visual inspection. Things are going to happen and this inspection in no way is a warranty or guarantee as to the condition of the property. Make sure to complete a final walk through of the property before the close of escrow.

This inspection does not include testing for radon, mold, termites and other wood destroying organisms, pests and rodents or other hazardous materials unless specifically requested.

We are always interested in advancing the quality of our service and our report. We welcome and value your input. We adhere to a high standard of professionalism and treat everyone with the utmost courtesy and respect.

We are proud of our service and trust you will be happy with the quality of our inspection and report. Please contact us with any concerns you may have regarding the report. We will be glad to discuss them with you.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

### Report Summary

This Report Summary will describe area(s) of concern that were observed at time of inspection by this inspector that may need some type of repair, replacement, service or further review. Keep in mind that all homes need some type of repair, even if only minor and generally older homes will need more repairs. All safety concerns mentioned within this report should be reviewed and repaired prior to occupancy. While every effort is made to identify existing and potential problems at the time of the inspection, it is not possible for a home inspector to foresee all problems that might arise in the future. This Report Summary is provided as a courtesy and cannot be considered a substitute for reading the entire report.

#### Utility Systems and Components

##### **Electrical Service Connection and Components: Inspected**

- Main panel not properly labeled; sub panel in garage has no door, open breaker area and not properly labeled

##### **Electrical: Interior / Bedroom Areas: Inspected**

- Bedrooms and upstairs hall missing smoke detectors, Missing CO2 detectors in upper and lower levels of home, cracked outlet in living room

##### **Electrical: Kitchen / Bathroom / Exterior Areas: Inspected**

- No GFCI's in kitchen, all 3 bathrooms, bar area

#### Grounds

##### **Driveway / Sidewalks: Inspected**

- Lifting spots in driveway, appears to be caused by tree roots

#### Structural Systems

##### **Floors: Inspected**

- Separated flooring in kitchen

##### **Ceiling: Inspected**

- Crack over entry door, right hand side; crack at wall leading to kitchen area, left hand side

##### **Door(s) (Interior & Exterior) includes Garage Door: Inspected**

- Exterior man door of garage is showing framing material at bottom; Front entry step should be as wide as the door and 3 ft. in length.

##### **Awning(s) / Patio cover(s) / Carport(s): Inspected**

- Dry rot on left side of 4x8 beam of back awning

##### **Stairways-Handrails-Guardrails (Interior & Exterior): Inspected**

- Interior handrail should return to wall at upper and lower ends

#### Roof and Attic

##### **Gutters and Down Spouts: Inspected**

- Gutters are pulling away from home, full of water

#### Fireplace & Chimney

##### **Chimney: Inspected**

- Missing and cracked parts of crown

#### Water Heating System(s)

##### **Water Heating System: Functional**

- No concerns observed with water heater. Penetrations through roof need to be sealed above water heater and furnace.

#### Pool / Spa

##### **Structure Condition, Decking and Coping: Inspected**

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED] Gridley, Ca 95948

---

- Width of pool deck appears to be narrow. Coping in some areas need repair. Rust and crack on diving board. Crack on ladder to pool.

**Gate & Fence: Inspected**

- No fence surrounding pool to keep children and/or animals out
- 

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Electrical System

Our inspection of Electrical System and components in accordance with industry standards of practice includes identifying the type and capacity of the service, evaluating panels, overload conductors, wires, panel grounds, the testing of a representative number of switches and outlets that were visible and accessible, and the presence or absence of smoke detector(s)/carbon monoxide detector(s). This report is to inform you of current condition as observed at time of inspection. We recommend that all electrical repairs and or replacements be evaluated and corrected by a qualified electrical contractor.

#### Electrical Service Connection and Components

##### General Observation

Inspected

Unsatisfactory

##### Service Connection

Location: Main Panel - Exterior wall of Garage

Services connection: Public Utilities (Underground Service)

Service on during inspection: Yes Type of wiring: Copper

Service size main panel: 120 / 240 Volt (Nominal) Amp: 200 Amp service

Service size sub panel: 120 / 240 Volt (Nominal) Amp: 100 Amp service

##### Electrical Observations

Main panel not properly labeled; sub panel in garage has no door, open breaker area and not properly labeled




#### Electrical: Interior / Bedroom Areas

##### Switches / Outlets / Fixtures / Smoke Detector(s) / CO Detector(s)

Inspected

Recommend Repair

Observation: Bedrooms and upstairs hall missing smoke detectors, Missing CO2 detectors in upper and lower levels of home, cracked outlet in living room



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection





### Electrical: Kitchen / Bathroom / Exterior Areas

#### Switches / Outlets / Fixtures

Inspected

Recommend Repair

**Observation:** No GFCI's in kitchen, all 3 bathrooms, bar area; missing GFCI's in rear and front exterior of home



## Plumbing Systems

Our inspection of the Plumbing Systems and components in accordance with industry standards of practice includes a visual examination of the accessible and visible plumbing fixtures and components. The plumbing system and their components are tested and observed using normal operating controls, testing functional flow and observance of any active leakage throughout fixture(s) and faucet(s). All underground and hidden piping and components, including water supply lines, waste lines, fuel lines, storage tanks & sprinkler systems are beyond the scope of this inspection. Leakage or corrosion in underground and hidden piping cannot be detected by a visual inspection, and for this reason we recommend further evaluation by a qualified contractor to confirm its actual condition. This report is to inform you of current condition as observed at time of inspection. We recommend that all material defects noted below be fully evaluated and/or corrected by a qualified plumbing contractor prior to the close of escrow or contingencies.

### Gas / Fuel Supply System

#### General Observation

Inspected

Satisfactory

#### Service Connection

**Location:** Exterior wall of Garage

**Services connection:** Public Utilities (Underground Service)

**Service on during inspection:** Yes

#### Further Comments

No concerns observed

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Water Supply System

#### General Observation

Inspected

Satisfactory

#### Service Connection

**Location:** Water meter with main shut off located next to street

**Services connection:** Public Utilities (Underground Service)

**Service on during inspection:** Yes

**Static water pressure reading (psi):** 30-40

**Type of supply lines:** Copper piping

#### Further Comments

No concerns observed

### Sewage Supply System

#### General Observation

Inspected

Satisfactory

#### Service Connection

**Location:** Cleanouts located side of home

**Services connection:** Public Utilities (Underground Service)

**Service on during inspection:** Yes

**Type of drain pipes:** ABS pipe

#### Further Comments

No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Grounds

Our inspection of the Grounds area(s) in accordance with industry standards of practice are inspected visually for positive grading and drainage that are essential to the welfare of a property and does not attempt to determine the condition of any underground piping, including municipal water, sewer service piping or septic systems. Also inspected are the trees and shrubbery that can cause foundation and or roof damage when growing too closely to the structure. While driveways and sidewalks of a residence may be dirt, gravel or paved with a hard, solid surface, such as concrete or asphalt. Some cracking in driveways and walkways can be expected; however, they should not cause a tripping hazard, erosion or in any way negatively impact the house. This report is to inform you of current condition as observed at time of inspection.

#### Front yard

##### General Observation

Inspected

Satisfactory

##### Description

Material: Grass / Vegetation

Further Comments: No concerns observed

#### Side yard(s)

##### General Observation

Inspected

Satisfactory

##### Description

Material: Grass / Vegetation

Further Comments: No concerns observed

#### Back yard

##### General Observation

Inspected

Satisfactory

##### Description

Material: Grass / Vegetation

Further Comments: No concerns observed

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Driveway / Sidewalks

#### General Observation

Inspected

Qualified Professional Recommended

#### Description

Material: Concrete

Further Comments: Lifting spots in driveway, appears to be caused by tree roots



### Fencing / Gate

#### General Observation

Inspected

Unsatisfactory

#### Description

Material: Wood

Further Comments: Garage side gate latch is rusted closed; Gate to pool drags on cement and does not close properly



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Tree's / Shrubby

#### General Observation

Inspected

Unsatisfactory

#### Description

**Further Comments:** Some shrubbery blocking pool deck



### Grading / Slope

#### General Observation

Inspected

Satisfactory

#### Description

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Structural Components / Foundation / Sub Areas

Our inspection of the Structural Components / Foundation / Sub Areas in accordance with industry standards of practice, that includes the visually accessible areas of carports, patio covers, awnings, decks, walls, flooring, ceilings, fascia, trim, soffits, balconies, doors, windows, basement and stairways. We visually inspect the foundation and look for any evidence of structural deficiencies, while foundation type and material of construction may defer such as concrete, masonry block, brick, stone and or wood foundation, they can experience some degree of cracking due to stress, settlement, shrinkage and various temperature change. We will not inspect any detached structures unless contracted to do so. This inspection does not include the geological conditions of the property, such as soil expansion or soil compaction. This inspector is not required to enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely affect the health of the home inspector or other persons. This inspector will not enter crawlspaces or any areas where headroom clearance is less than 18 inches and the width of the access opening is less than 18 inches by 24 inches or where inspector reasonably determines conditions or materials are hazardous to his health or safety. This report is to inform you of current condition as observed at time of inspection.

#### Foundation

##### General Observation

Inspected

Satisfactory

##### Description

Type of Foundation(s) Slab on Grade Foundation

Further Comments: No concerns observed

#### Floors

##### General Observation

Inspected

Recommend Repair

##### Description

Material: Carpet, bamboo, tile

Further Comments: Separated flooring in kitchen



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Ceiling

#### General Observation

Inspected

Unsatisfactory

#### Description

**Material:** Drywall / Plaster

**Further Comments:** Crack over entry door, right hand side; crack at wall leading to kitchen area, left hand side



### Walls (Interior)

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Drywall / Plaster

**Further Comments:** No concerns observed

### Walls (Exterior)

#### General Observation

Inspected

Recommend Repair

#### Description

**Material:** Stucco

**Further Comments:** Crack in stucco near slider from kitchen





## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Window(s)

#### General Observation

Inspected

Recommend Repair

#### Description

**Material:** Aluminum (single pane)

**Further Comments:** Window trim damaged at exterior garage window, lower right side



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Door(s) (Interior & Exterior) includes Garage Door

#### General Observation

Inspected

Recommend Repair

#### Description

**Type:** Solid Core (two panel), 2 sliders, hollow core, single and two car garage doors(Metal)

**Further Comments:** Exterior man door of garage is showing framing material at bottom; Front entry step should be as wide as the door and 3 ft. in length.



### Awning(s) / Patio cover(s) / Carport(s)

#### General Observation

Inspected

Recommend Repair

#### Description

**Material:** Wood structure

**Further Comments:** Dry rot on left side of 4x8 beam of back awning

### Stairways-Handrails-Guardrails (Interior & Exterior)

#### General Observation

Inspected

Recommend Repair

#### Description

**Material:** Hardwood

**Further Comments:** Interior handrail should return to wall at upper and lower ends

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Roof and Attic

Our inspection of the Roof and Attic area(s) in accordance with industry standards of practice includes a visual observation of the roof covering, gutters, downspouts, vents, flashings, chimney, skylight and other roof penetrations within the limits of accessibility. The inspector may walk the surface of a roof in order to inspect it and its components but may inspect it by other means if the roof cannot be safely accessed, due to its height, weather conditions, or if the roofing material could be damaged by foot traffic. The inspector is not required to, predict the service life expectancy or inspect underground downspout diverter pipes, remove snow ice or debris, or inspect antennae, lighting arrestors or similar attachments. All roofing types require some type of annual maintenance (some types more frequent than others). Failure to perform routine maintenance can result in leaks and accelerate roof covering and flashings deterioration. An inspector cannot guarantee a roof is leak free, only observation during a prolonged rainfall can determine this. This report is to inform you of current condition as observed at time of inspection. We do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best as we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

#### Roof Structure


##### General Observation

Inspected

Satisfactory

##### Description

**Further Comments:** No concerns observed



#### Roof Covering

##### General Observation

Inspected

Satisfactory

##### Description

**Material:** Galvanized steel

**Viewed from:** Walked the roof

**Further Comments:** No concerns observed

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Roof Slope

#### General Observation

Inspected

Satisfactory

#### Description

Further Comments: Minimum Slope

### Gutters and Down Spouts

#### General Observation

Inspected

Recommend Repair

#### Description

Material: Metal

Further Comments: Gutters are pulling away from home, full of water



### Flashing

#### General Observation

Inspected

Satisfactory

#### Description

Material: Galvanized metal

Further Comments: No concerns observed

### Ventilation

#### General Observation

Inspected

Satisfactory

#### Description

Further Comments: No concerns observed

### Attic Structure

#### General Observation

Inspected

Satisfactory

#### Description

Viewed From: By entering crawl space

Further Comments: Low on insulation

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Attic Vents

#### General Observation

Inspected

Satisfactory

#### Description

**Type:** Gable vents

**Further Comments:** No concerns observed

### Insulation

#### General Observation

Inspected

Satisfactory

#### Description

**Materials:** Fiberglass batt

**Further Comments:** Low on insulation

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Fireplace(s) / Chimney(s)

Our inspection of the Fireplace/Chimney area(s) in accordance with industry standards of practice includes a visual observation of all accessible components. While there are three basic types of chimney's, single-walled metal, masonry, and pre-fabricated metal also referred to as factory-built ones. Masonry and factory-built ones are a commonplace in residential homes. Our inspection of them conforms to industry standards, and is that of a generalist and not a specialist. While some areas of the chimney flue cannot be adequately viewed during a home inspection and does not include the use of specialized equipment, we will not guarantee their integrity or drafting ability and recommend that they be more thoroughly evaluated before the close of escrow. We will not move furniture, lift carpets or rugs. This report is to inform you of current condition as observed at time of inspection.



#### Firebox and Butt Wall

##### General Observation

Inspected

Satisfactory

##### Description

Material: Brick

Further Comments: No concerns observed

#### Damper

##### General Observation

Inspected

Satisfactory

##### Description

Further Comments: No concerns observed

#### Flue Vent Connector, Flue Pipe

##### General Observation

Inspected

Satisfactory

##### Description

Material: Lined with clay flue tile liners

Further Comments: No concerns observed

#### Hearth (Inner and Outer)

##### General Observation

Inspected

Satisfactory

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Description

**Material:** Red brick

**Further Comments:** No concerns observed

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Door(s) or Enclosures

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Glass doors tempered

**Further Comments:** No concerns observed

### Mantle

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Wood

**Further Comments:** No concerns observed

### Chimney

#### General Observation

Inspected

Recommend Repair

#### Description

**Viewed from:** Walked the roof

**Further Comments:** Missing and cracked parts of crown



### Chimney Top (Chimney cap, Spark arrester, Hood)

#### General Observation

Inspected

Satisfactory

#### Description

**Type:** Standard Chimney Cap

**Further Comments:** No concerns observed

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Fuel Source

#### General Observation

Inspected

Satisfactory

#### Description

**Type:** Wood

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Interior / Living Areas

Our inspection of the Interior / Living area(s) includes dining room, den, living room, formal room, office, bar, laundry room, hallways and stairways in accordance with industry standards of practice includes the visually accessible areas of walls, floors, ceilings, cabinets and closets, and includes the testing of a representative number of windows, doors, switches and outlets, also the plumbing system if present and their components are tested and observed, which includes testing functional flow and leaks throughout fixture(s) and faucet(s). Inspect drain, waste and vent system and report on deficiencies. However, we do not move furniture, lift carpets or rugs, empty closets or cabinets. This report is to inform you of current condition as observed at time of inspection.

#### Flooring

##### General Observation

Inspected

Satisfactory

##### Description

**Material:** Carpet and tile

**Further Comments:** No concerns observed

#### Walls and Ceiling (Interior)

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** Drywall / Plaster

**Further Comments:** No concerns observed

#### Window(s)

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** Aluminum (single pane)

**Further Comments:** No concerns observed

#### Door(s)

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** Hollow core

**Further Comments:** No concerns observed



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Closet(s)

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Hollow core

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Bedroom Areas

Our inspection of the Bedroom area(s) in accordance with industry standards of practice includes the visually accessible areas of walls, floors, ceilings, cabinets and closets, and includes the testing of a representative number of windows, doors, switches and outlets. However, we do not evaluate window treatments, or move furniture, lift carpets or rugs, empty closets or cabinets. This report is to inform you of current condition as observed at time of inspection.

#### Flooring

##### General Observation

Inspected

Satisfactory

##### Description

Material: Carpet

Further Comments: No concerns observed

#### Walls and Ceiling (Interior)

##### General Observation

Inspected

Satisfactory

##### Description

Type: Drywall / Plaster

Further Comments: No concerns observed

#### Window(s)

##### General Observation

Inspected

Satisfactory

##### Description

Type: Aluminum (single pane)

Further Comments: No concerns observed

#### Door(s)

##### General Observation

Inspected

Satisfactory

##### Description

Type: Hollow core

Further Comments: No concerns observed

#### Closet(s)

##### General Observation

Inspected

Satisfactory

##### Description

Material: Louvered door(s)

Further Comments: No concerns observed

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Laundry Room

Our inspection of the Laundry room area(s) in accordance with industry standards of practice includes a visual examination of the readily accessible areas of the walls, floor, ceiling, cabinets, countertops and plumbing fixtures. The plumbing system and their components are tested and observed using normal operating controls, which includes testing functional flow and observance of any active leakage throughout fixture(s) and faucet(s). Exhaust vent fans and their ductwork are tested for their proper operation. Inspect drain, waste and vent system and report on deficiencies. Very minor imperfections can allow water intrusion into the walls or floor areas and cause damage. We will not attempt to move furniture, lift carpets or rugs, empty closets or cabinets. This report is to inform you of current condition as observed at time of inspection.

#### Cabinet(s)

##### General Observation

Inspected

Satisfactory

##### Description

**Material:** Wood Cabinets

**Further Comments:** No concerns observed

#### Floor Covering (Laundry)

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** Vinyl sheeting

**Further Comments:** No concerns observed

#### Exhaust Venting

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** Metal Flex

**Further Comments:** No concerns observed

#### Laundry Plumbing Supply (Gas / Water)

##### General Observation

Inspected

Satisfactory

##### Description

**Type:** CPVC and Steel

**Further Comments:** No concerns observed

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** 670 Colusa Highway, Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Laundry Plumbing Drain and Vent System

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** ABS pipe

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Bathroom(s)

Our inspection of the Bathroom area(s) in accordance with industry standards of practice includes a visual examination of the readily accessible areas of the walls, floor, ceiling, cabinets, countertops and plumbing fixtures. The plumbing system and their components are tested and observed using normal operating controls, which includes flushing toilet(s), testing functional flow and observance of any active leakage throughout fixture(s) and faucet(s). Exhaust vent fans and their ductwork are tested for their proper operation. Shower pans/Tubs are visually checked for possible leakage concerns, but leaks often do not show except when the shower/tub is in actual use. Determining whether shower pans, tub/shower surrounds are watertight is beyond the scope of this inspection. It is very important to maintain all grout, caulking and other sealants used in the bathroom areas. Very minor imperfections can allow water intrusion into the walls or floor areas and cause damage. We will not attempt to move furniture, lift carpets or rugs, empty closets or cabinets. This report is to inform you of current condition as observed at time of inspection.

#### Cabinet(s)

##### [General Observation](#)

Inspected

Satisfactory

##### [Description](#)

Material: Wood Cabinets

Further Comments: No concerns observed

#### Countertop(s)

##### [General Observation](#)

Inspected

Satisfactory

##### [Description](#)

Material: Granite

Further Comments: No concerns observed

#### Floor Covering (Bathroom)

##### [General Observation](#)

Inspected

Satisfactory

##### [Description](#)

Type: Tile

Further Comments: No concerns observed

#### Toilet(s)

##### [General Observation](#)

Inspected

Satisfactory

##### [Description](#)

Type: Porcelain

Further Comments: No concerns observed

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Shower/Tub (Surround)

#### General Observation

Inspected

Satisfactory

#### Description

**Type:** Tile

**Further Comments:** No concerns observed

### Shower Enclosure

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Framed shower door

**Further Comments:** No concerns observed

### Bathroom Plumbing

#### General Observation

Inspected

Satisfactory

#### Description

**Type:** Copper and ABS

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Kitchen

Our inspection of the Kitchen area(s) in accordance with industry standards of practice includes the visually accessible areas of walls, floors, ceilings, cabinets and closets, and includes the testing of a representative number of windows and interior doors, switches and outlets, also the plumbing system and their components are tested and observed, which includes testing functional flow and leaks throughout fixture(s) and faucet(s). Inspect drain, waste and vent system and report on deficiencies. We will not attempt to move furniture, lift carpets or rugs, empty closets or cabinets. This report is to inform you of current condition as observed at time of inspection.

#### Cabinet(s)

##### General Observation

Inspected

Satisfactory

##### Description

Material: Wood Cabinets

Further Comments: No concerns observed

#### Countertop(s)

##### General Observation

Inspected

Satisfactory

##### Description

Material: Granite

Further Comments: No concerns observed

#### Floor Covering (Kitchen)

##### General Observation

Inspected

Recommend Repair

##### Description

Material: Bamboo

Further Comments: Separated flooring in kitchen



## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Closet(s) / Panty

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Wood door(s)

**Further Comments:** No concerns observed

### Kitchen Plumbing

#### General Observation

Inspected

Satisfactory

#### Description

**Material:** Copper and ABS

**Further Comments:** No concerns observed

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED] Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Kitchen Appliances

We perform a visual and brief operational inspection of built-in appliances listed within this report. This inspector will not operate: Any system that is shut down, any system that does not function properly, any system that does not turn on with the use of normal operating controls, any gas appliance that requires the use of a match or other remote burner lighting device, or determine leakage from microwave ovens, Inspector will not move any personal items or other obstructions, Inspector will not dismantle, open, or uncover any system or component or enter or access any area which may, in the opinion of the inspector, be unsafe or where damage might occur. The following items are excluded from this report; Portable appliances, appliances timers & thermostats, water filtration devices, icemakers, instant hot water makers, clothes washer & dryer operation, appliances that are concealed. While kitchen appliances are subject to unpredictable life expectancy and may require repair or replacement even though functional at time of inspection, NO warranty is expressed or implied. Clients are advised to purchase a home protection plan because appliances, including new appliances, can fail at any time, including immediately after the inspection. Older appliances five years or older of course, are more prone to failure. While every effort was made by this inspector to find all areas of concern, some areas can go unnoticed. Any repair items mentioned within this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection needed or repair issues as it relates to the comments within this inspection report.

#### Refrigerator / Freezer

##### General Observation

Inspected

Satisfactory

##### Description

Location: Kitchen - Free standing

##### Further Comments

No concerns observed

#### Microwave

##### General Observation

Inspected

Satisfactory

##### Description

Location: Kitchen - Build in cabinet

##### Further Comments

No concerns observed





## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Range Oven

#### General Observation

Inspected

Satisfactory

#### Description

Location: Kitchen - Build in cabinet

#### Further Comments

No concerns observed

### Stove Top

#### General Observation

Inspected

Satisfactory

#### Description

Location: Kitchen - Build in counter

#### Further Comments

No concerns observed



### Exhaust fan / light

#### General Observation

Inspected

Satisfactory

#### Description

Location: Kitchen - Build in cabinet

#### Further Comments

No concerns observed

### Dishwasher

#### General Observation

Inspected

Satisfactory

#### Description

Location: Kitchen - Free standing between counter/cabinets

#### Further Comments

No concerns observed

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Food Waste Disposer

#### General Observation

Inspected

Satisfactory

#### Description

Location: Kitchen (inside sink base cabinet)

#### Further Comments

No concerns observed



This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED], Gridley, Ca 95948

**Inspected**

**Not Inspected**

**Not Present**

**Damaged / Repair**

**Safety Hazard**

Color of selection below will indicate the level of concern for each area at time of inspection

### Heating and Cooling

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee.

#### Heating System

##### General Observation

**Inspected**

**Satisfactory**

**Furnace Name:** Lennox

**Year Model:** 1995

**Model #:**

**Serial #:**

**Heat source type:** Forced Air System

**Fuel type:** Natural Gas

**Vent type:** Dilutant Flue / Flue Dilution System

**Location:** Garage

##### Further Comments

No concerns observed



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Cooling System

#### General Observation

Inspected

Satisfactory

Furnace Name: Lennox

Year Model: 1995

Model #: HS25-651-2P

Serial #: 5894M02066

Cooling type: Central Air Conditioning System

Location: Back yard

#### Further Comments

No concerns observed; Return air grill missing filter.



This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.

## Dependable Home Inspections

**Date Of Inspection:** March 13, 2019

**Inspection Address:** [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Water Heating System(s)

There are a wide variety of residential water heaters systems that range in capacity from fifteen to one hundred gallons. They can be expected to last at least as long as their warranty, or from five to eight years, but they will generally last longer. However, few of them last longer than fifteen or twenty years and many eventually leak. So it is always a good idea to have them installed over a drain pan plumbed to the exterior. Also, it is very important to flush them annually to remove loose sediment that includes the calcium chloride bi-products of many water softening systems. The water temperature should be set at a minimum range of 110 degrees Fahrenheit to kill microbes and a maximum of 140 degrees to prevent scalding. Also, water heaters can be dangerous if they are not seismically secured and equipped with either a pressure/temperature relief valve and discharge pipe plumbed to the exterior, or a Watts 210 gas shut-off valve. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee.

#### Water Heating System

##### General Observation

Functional

Satisfactory

**Brand:** AOSmith

**Year Model:** 2007

**Model #:** GVR50100

**Serial #:** K07J060039

**Type of system:** Gas demand water heater

**Fuel type:** Natural Gas

**Tank capacity:** 50 gallon

**Location:** Garage

**Ventilation type:** Natural draft - galvanized steel pipe

##### Further Comments

No concerns observed with water heater. Penetrations through roof need to be sealed above water heater and furnace.



This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Pool / Spa

Our inspection of the Pool / Spa area(s) in accordance with industry standards of practice includes the visually accessible areas of the pool, spa, pumps, heater, visible piping, liner, ladder, steps, railing, diving board, a visual exterior inspection for leaks. We visually inspect the Pools foundation and look for any evidence of structural deficiencies. The plumbing system and their components also are tested and observed for functional flow and leaks throughout system. This report is to inform you of current condition as observed at time of inspection.

#### Electrical / Lighting / Outlets

##### General Observation

Inspected

Satisfactory

##### Description

Further Comments: No concerns noted

#### Structure Condition, Decking and Coping

##### General Observation



Inspected

Recommend Repair

##### Description

Material: Concrete with aggregate finish

Further Comments: Width of pool deck appears to be narrow. Coping in some areas need repair. Rust and crack on diving board. Crack on ladder to pool.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Pump(s) / Jets

#### General Observation

Inspected

Additional Inspection Needed

#### Description

Further Comments: Pool pumps not on at time of inspection, crack in equipment



### Filter / Skimmer and Basket


#### General Observation

Inspected

Needs Servicing

#### Description

Further Comments: Skimmer and basket need cleaning



### Pressure Gauge

#### General Observation

Inspected

N/A

#### Description

Further Comments: No pressure observed

## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Pool / Spa Heating System(s)

#### General Observation

Inspected

#### Description

Type:

Further Comments: Spa was drained; No evidence of leaks; No emergency shutoff noted.



## Dependable Home Inspections

Date Of Inspection: March 13, 2019

Inspection Address: [REDACTED], Gridley, Ca 95948

Inspected

Not Inspected

Not Present

Damaged / Repair

Safety Hazard

Color of selection below will indicate the level of concern for each area at time of inspection

### Plumbing

#### General Observation

Inspected

Satisfactory

#### Description

Material: PVC piping

Further Comments: No concerns observed

### Water Condition

#### General Observation

Inspected

Satisfactory

#### Description

Further Comments: Clear

### Timer

#### General Observation

Inspected

Satisfactory

#### Description

Type: Single enclosure unit (125 volt )

Further Comments: Not labeled



### Gate & Fence

#### General Observation

Inspected

Unsatisfactory

#### Description

Material: Wrought iron

Further Comments: No fence surrounding pool to keep children and/or animals out

This Home Inspection Field Report is confidential and has been produced in accordance with our signed contract agreement and is subject to the terms and conditions agreed upon therein.