AME	1. CONTRACT ID CO	ODE	PAGE (	OF PAGES				
2. AMENDME	NT/MODIFICATION NUMBER	3. EFFECTIVE DATE	4. REQUISITION/PURCHASE	REQUISITION NUMBER	5. PROJECT	NUMBER	(If applicable)	
00003		05/013/2019			P/N 8617	883		
6. ISSUED B	Y CODE		7. ADMINISTERED BY (If other than Item 6) CODE					
1240 E9th	U CLEVELAND Street, Room 2179 , Ohio 44199	Same as #6.						
8. NAME AND	ADDRESS OF CONTRACTOR (Number, stre	eet, county, State and ZIP Co	ode) (	(X) 9A. AMENDMEI	NT OF SOLICIT	ATION NU	 JMBER	
				70Z08319Rl 9B. DATED (SEE 04/18/2019 10A. MODIFICAT	E ITEM 11)	RACT/OR	DER NUMBER	
CODE	FA	CILITY CODE						
11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS								
(a) By complet or (c) By separ RECEIVED AT by virtue of this communication		copies of the amendment cludes a reference to the sol IPT OF OFFERS PRIOR TO eady submitted, such change mendment, and is received p d)  PLIES ONLY TO MODE CONTRACT/ORDED SUANT TO: (Specify author PRIOR IS MODIFIED TO RETEM 14, PURSUANT TO THE ENTERED INTO PURSUANT	nt; (b) By acknowledging receipicitation and amendment numb THE HOUR AND DATE SPECE THE HOUR AND DATE SPECE THE MADE TO THE HOUR AND DATE SPECE TO THE HOUR AND DATE SPECE TO THE OPENING HOUR AND DESCRIPTIONS OF CONTRIBUTIONS OF	ot of this amendment or bers. FAILURE OF YOU CIFIED MAY RESULT I ctronic communication, ate specified.  TRACTS/ORDER RIBED IN ITEM 14 TH IN ITEM 14 ARE MA	n each copy of the Communication	EDGMENT OF YOUR etter or ele	TO BE , OFFER. If etronic	
E. IMPORT	I TANT: Contractor	required to sign this o	document and return	copies	s to the issui	ng office	4	
				root subject metter whe	ro foosible l			
Request F BALTIMOR 1. Request Except as provi	or Proposal 70Z08319RPBA0030RE, MARYLAND., U. S. Coast Gut For Information responses date	00; CPOP REPAIR Vuard Yard Baltimore	WEST WHARF, U.S. , Baltimore, Maryland ference photos A-9 th	COAST GUARD . is amended as nrough A-24. d, remains unchanged a	YARD BA follows:	and effect.		
IJA. NAIVIE AI	ND TITLE OF SIGNER (Type or print)		15. 1. IV WILL THE THE OF C	25,7110,671110 01110	(1.5 pc of pil	,		
			Verona M Wolfe					
15B. CONTRA	15B. CONTRACTOR/OFFEROR 15C. DATE SIGNED			6B. UNITED STATES OF AMERICA, WOLK 5113119				
(S	ignature of person authorized to sign)		(Signature o	of Contracting Officer)		/	1011	

RREQUEST FOR PROPOSAL 70Z08319RPBA00300; CPOP REPAIR WEST WHARF, U.S. COAST GUARD YARD BALTIMORE, BALTIMORE, MARYLAND., Request For Information Responses A00003 5/13/19

<u>QUESTION</u>: Can you provide the underwater inspection report and video/photos of the most recent inspection.


ANSWER: See reference photos A-9 through A-24

<u>QUESTION:</u> Can you provide a US Coast Guard approved source(s) for the specified timber to be used for piling repairs?

ANSWER: This is the responsibility of the General Contractor

<u>QUESTION</u>: Can you provide any more description/details for the galvanized materials to be used in pile repairs?

ANSWER: See section 06 05 23 TIMBER CONNECTORS



**Photo A-9:** Deck Plank – Typical Condition (underside view looking up from waterline)




Photo A-10: Deck Plank – Deterioration with Active Fill Loss (underside view looking up from waterline)



Photo A-11: Pile Cap – Typical Condition



Photo A-12: Pile Cap — Typical Condition




Photo A-13: Pile Cap Splice and Hardware — Typical Condition



Photo A-14: Pile Cap Splice Hardware – up to 75% section loss.



Photo A-15: Timber Pile – Typical Condition



**Photo A-16:** Timber Sheet Pile Wall – Typical Condition



Photo A-17: Sinkhole at Sta. 2+00 (sinkhole extends to Deck Planks)






Photo A-19: Sinkhole at Sta. 2+62





Photo A-21: Void at Sta. 5+55 (Pile Cap at bottom of photo, deteriorated Deck Planks to right and left)



Photo A-22: Void at Sta. 5+55



Photo A-23: Void with scale measurement at Sta. 5+55

