

United States Department of the Interior BUREAU OF INDIAN AFFAIRS

EASTERN OKLAHOMA REGION OSAGE AGENCY POST OFFICE BOX 1539 PAWHUSKA, OKLAHOMA 74056-1539



MAY 24'2013

OPERATIONS REPORT FOR WEEK ENDING MAY 24, 2013

LOCATIONS:

P4-20 NW 31-25-12

Performance Energy Resources (Woolaroc)

Mississippi Lime @ 2200'

Elevation: 941' G.L.

Location: 330' FNL - 330' FWL

COMPLETIONS:				
	W42	NE 10-27-05	Chaparral Energy, LLC TD @ 2350' Elevation: 1068' G.L.	Completion – Inj
			Elevation; 1008 G.L.	Location: 1662' FNL – 661' FEL
	2A	NW 16-27-07	Nadel and Gussman, LLC TD @ 3328'	Completion – SWD
			Elevation: 1240' G.L.	Location: 990' FNL – 330' FWL
	2A-4	NW 04-26-07	Nadel and Gussman, LLC TD @ 3382'	Completion – SWD
			Elevation: 1247' G.L.	Location: 150' FNL – 430' FWL
	5H	NW 08-25-09	Encana Oil & Gas (USA) TD @ 2339' Elevation: 820' G.L.	Completion – Oil 148 Oil, 129 Gas, 116 Water Location: 315' FNL – 2010' FWL
	10	SE 25-25-09	Beckham & Butler Production TD @ 2036' Elevation: 851' G.L.	Completion – Oil 8 Oil, Some Gas, 85 Water Location: 570' FSL – 1475' FWL
	9	NE 36-25-09	Beckham & Butler Production TD @ 2012' Elevation: 844' G.L.	Completion – Oil 14 Oil, Some Gas, 200 Water Location: 540' FNL – 795' FWL
	46	NE 36-25-09	Beckham & Butler Production TD @ 1990' Elevation: 833' G.L.	Completion – Oil 6 Oil, Some Gas, 126 Water Location: 1604' FNL – 1115' FEL
	26	NE 15-24-10	Beckham & Butler Production TD @ 2037' Elevation: 929' G.L.	Completion – Oil 6 Oil, Some Gas, 114 Water Location: 475' FSL – 1468' FWL
	24	SE 15-24-10	Beckham & Butler Production TD @ 2012' Elevation: 900' G.L.	Completion – Oil 12 Oil, 10,000 Gas, 35 Water Location: 380' FNL – 1463' FWL

COMPLETIONS CONTINUED:

2A NW 31-25-10 Beckham & Butler Production Completion - Oil

TD @ 2030'

6 Oil, 30 Gas, 200 Water

Elevation: 885' G.L.

Location: 1210' FNL - 440' FWL

80-A1 NW 17-26-11

Trailblazer Energy LLC

Completion – Oil

TD @ 1672'

10 Oil, 50 Water

Elevation: 853' G.L.

Location: 952' FNL - 590' FWL

COMPLETION CORRECTION:

10-5 NE 08-24-12

Performance Operating Co.

Township correction from 21N to 24N. Reported Week Ending May 10, 2013.

11-15 NW 09-25-12

Performance Operating Co.

Location: 800' FNL - 660' FWL

Location correction. Reported Week Ending May 10, 2013.

30-1 SW 30-26-12 NTR Energy, LLC

Location: 330' FSL - 14200' FWL

Location correction. Reported Week Ending May 10, 2013.

SUMMARY

1 LOCATION 11 COMPLETIONS **3 COMPLETION CORRECTIONS** 3 WORKOVERS

Larraine Wilcz Superintendent