



IN REPLY REFER TO:

United States Department of the Interior
BUREAU OF INDIAN AFFAIRS
EASTERN OKLAHOMA REGION
OSAGE AGENCY
POST OFFICE BOX 1539
PAWHUSKA, OKLAHOMA 74056-1539



JUL 31 2013

OPERATIONS REPORT FOR WEEK ENDING JULY 26, 2013

LOCATION:

79B NE 01-21-07	Synergex, Inc. Bartlesville @ 2187' Elevation: 730' G.L.	(Boston) Location: 150' FSL – 150' FEL
-----------------	--	---

RENEWALS:

K-14 SE 23-25-06	Performance Energy Resources Woodford @ 2200' Elevation: 1074' G.L.	(Solomon Creek) Location: 1200' FSL – 660' FEL
C-2 NE 26-25-06	Performance Energy Resources Woodford @ 2200' Elevation: 1050' G.L.	(Burbank) Location: 330' FSL – 990' FWL
C-1 NW 26-25-06	Performance Energy Resources Woodford @ 2200' Elevation: 1056' G.L.	(Burbank) Location: 330' FNL – 660' FEL
C-6 NW 26-25-06	Performance Energy Resources Woodford @ 2200' Elevation: 1021' G.L.	(Burbank) Location: 660' FSL – 660' FEL
#17 NE 10-25-09	Performance Energy Resources Woodford @ 2200' Elevation: 801' G.L.	(Pawhuska) Location: 330' FNL – 330' FEL
4A SE 10-25-09	Performance Energy Resources Woodford @ 2200' Elevation: 807' G.L.	(Pawhuska) Location: 50' FNL – 1100' FWL
20-17 SW 20-28-09	Performance Energy Resources Woodford @ 2200' Elevation: 949' G.L.	(Pawhuska) Location: 330' FSL – 330' FWL
30-12 SE 30-28-09	Performance Energy Resources Woodford @ 2200' Elevation: 1018' G.L.	(Landon) Location: 990' FSL – 330' FEL

RENEWALS CONTINUED:

30-14	SE 30-28-09	Performance Energy Resources (Landon) Woodford @ 2200' Elevation: 1002' G.L.	Location: 330' FNL – 330' FEL
30-15	SE 30-28-09	Performance Energy Resources (Landon) Woodford @ 2200' Elevation: 1018' G.L.	Location: 330' FNL – 990' FWL
30-11	SW 30-28-09	Performance Energy Resources (Landon) Woodford @ 2200' Elevation: 1094' G.L.	Location: 330' FSL – 330' FEL
09-114	NW 24-26-10	Performance Energy Resources (Okesa) Woodford @ 2200' Elevation: 902' G.L.	Location: 330' FNL – 660' FWL
19-19	NE 19-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 884' G.L.	Location: 790' FNL – 330' FEL
19-20	NE 19-27-10	Performance Energy Resources (Domes) Woodford @ 2200' Elevation: 912' G.L.	Location: 990' FNL – 990' FWL
19-21	NE 19-27-10	Performance Energy Resources (Domes) Woodford @ 2200' Elevation: 930' G.L.	Location: 330' FSL – 990' FEL
20-12	NE 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 839' G.L.	Location: 330' FSL – 990' FWL
20-14	NE 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 887' G.L.	Location: 990' FSL – 330' FWL
20-15	NW 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 867' G.L.	Location: 330' FSL – 330' FEL
20-9	SE 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 955' G.L.	Location: 330' FSL – 990' FWL
20-10	SE 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 923' G.L.	Location: 990' FNL – 990' FWL

RENEWALS CONTINUED:

20-11	SE 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 828' G.L.	Location: 330' FNL – 990' FEL
20-16	SW 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 862' G.L.	Location: 330' FNL – 990' FWL
20-17	SW 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 924' G.L.	Location: 990' FSL – 990' FEL
20-18	SW 20-27-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 884' G.L.	Location: 990' FSL – 990' FWL
11-1	SW 26-28-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 911' G.L.	Location: 330' FSL – 330' FEL
26-2	SW 26-28-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 910' G.L.	Location: 330' FNL – 330' FEL
26-6	SW 26-28-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 956' G.L.	Location: 660' FSL – 990' FWL
22-05	NE 22-29-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 790' G.L.	Location: 430' FNL – 330' FEL
22-02	SE 22-29-10	Performance Energy Resources (Turkey Creek) Woodford @ 2200' Elevation: 766' G.L.	Location: 990' FNL – 330' FEL
23-04	NW 23-29-10	Performance Energy Resources (Turkey Creek) Woodford @ 2200' Elevation: 851' G.L.	Location: 990' FSL – 330' FWL
23-01	SW 23-29-10	Performance Energy Resources (Turkey Creek) Woodford @ 2200' Elevation: 762' G.L.	Location: 575' FSL – 330' FWL
23-03	SW 23-29-10	Performance Energy Resources (Turkey Creek) Woodford @ 2200' Elevation: 783' G.L.	Location: 330' FNL – 330' FWL

RENEWALS CONTINUED:

25-01	NW 25-29-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 782' G.L.	Location: 990' FSL – 330' FEL
26-01	NE 26-29-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 760' G.L.	Location: 330' FSL – 330' FWL
26-04	NW 26-29-10	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 755' G.L.	Location: 330' FSL – 990' FWL
28-2	SW 28-24-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 707' G.L.	Location: 330' FNL – 330' FWL
28-5	SW 28-24-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 700' G.L.	Location: 330' FNL – 330' FEL
10-2	SE 29-25-11	Performance Energy Resources (Quapaw) Woodford @ 2200' Elevation: 951' G.L.	Location: 1150' FNL – 330' FWL
11-5	SW 29-25-11	Performance Energy Resources (Quapaw) Woodford @ 2200' Elevation: 832' G.L.	Location: 990' FSL – 330' FWL
5-5	NW 05-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 852' G.L.	Location: 990' FNL – 330' FWL
#6-7	NE 06-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 870' G.L.	Location: 990' FNL – 330' FWL
#6-5	NW 06-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 876' G.L.	Location: 330' FSL – 990' FEL
#6-6	NW 06-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 857' G.L.	Location: 990' FSL – 330' FEL
#6-8	SE 06-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 885' G.L.	Location: 330' FSL – 990' FEL

RENEWALS CONTINUED:

#7-4	NE 07-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 936' G.L.	Location: 990' FNL – 330' FWL
10-1	SE 10-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 940' G.L.	Location: 990' FSL – 990' FEL
10-4A	NE 15-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 890' G.L.	Location: 280' FNL – 380' FWL
10-18	NW 28-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 953' G.L.	Location: 330' FSL – 330' FWL
10-21	NW 28-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 893' G.L.	Location: 330' FSL – 990' FWL
10-19	NE 29-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 932' G.L.	Location: 990' FSL – 990' FEL
10-20	NE 29-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 965' G.L.	Location: 990' FSL – 330' FEL
30-6	NE 30-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 804' G.L.	Location: 1060' FSL – 330' FEL
30-4	SE 30-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 910' G.L.	Location: 330' FNL – 990' FWL
11-2	SW 30-27-11	Performance Energy Resources (Domes Pond) Woodford @ 2200' Elevation: 795' G.L.	Location: 330' FNL – 330' FWL
#21-20	NW 21-24-12	Performance Energy Resources (Avant) Woodford @ 2200' Elevation: 833' G.L.	Location: 330' FNL – 330' FWL
P4-26	SE 30-25-12	Performance Energy Resources (N. Ochelata) Woodford @ 2200' Elevation: 809' G.L.	Location: 990' FSL – 330' FWL

RENEWALS CONTINUED:

P4-24 SW 30-25-12	Performance Energy Resources (N. Ochelata) Woodford @ 2200' Elevation: 900' G.L.	Location: 415' FSL – 330' FEL
28-3 SW 28-26-12	Performance Energy Resources (Bartlesville Dewey Dist) Woodford @ 2200' Elevation: 869' G.L.	Location: 1320' FSL – 560' FEL
28-4 SW 28-26-12	Performance Energy Resources (Bartlesville Dewey Dist) Woodford @ 2200' Elevation: 895' G.L.	Location: 330' FSL – 1320' FEL
08-1A NW 30-27-12	Performance Energy Resources (Bartlesville Dewey Dist) Woodford @ 2200' Elevation: 863' G.L.	Location: 680' FNL – 580' FEL

SUMMARY

1 LOCATION

60 RENEWALS

Carla Norman

ACTING Superintendent