



SHARP IRON

G R O U P



STANDARD LEAD TIMES

- ✓ Burn-to-Shape
- ✓ Burn and Form
- ✓ Machining - simple
- ✓ Machining - complex
- ✓ Fabrications - simple
- ✓ Fabrications - complex
- ✓ Machined Fabrications - simple
- ✓ Machined Fabrications - complex

Stock Material (or customer supplied)

2 wks (14 days)
2 wks (14 days)
3 wks (21 days)
4 wks (28 days)
4 wks (28 days)
5 wks (35 days)
6 wks (42 days)
7 wks (49 days)

Non-Stock Material

3 wks (21 days)
3 wks (21 days)
4 wks (28 days)
5 wks (35 days)
5 wks (35 days)
6 wks (42 days)
7 wks (49 days)
8 wks (56 days)

OTHER SERVICES

- ✓ Plate Rolling
- ✓ Structural Rolling
- ✓ Stress Relief
- ✓ Paint only - simple
- ✓ Paint only - complex
- ✓ Subcontracted Processes
- ✓ Special Fabrication Projects

1 wk (7 days)
1 wk (7 days)
1 wk (7 days)
2 wks (14 days)
3 wks (21 days)
Add 2 wks (14 days)
As Quoted

2 wks (14 days)
2 wks (14 days)
customer supplied
customer supplied
customer supplied

**SHARP PEOPLE. SHARP QUALITY.
SHARP IRON.**

Phone: 940.766.4545 Toll Free: 888.687.2209
www.SharpIronGroup.com

