




# B7


<b>FUNCTION</b>	Indicator light SX82 series
<b>AMBIENT TEMPERATURE</b>	120 °C
<b>GWT</b>	850 °C
<b>GWT NO FLAME (&lt;2sec)</b>	650 °C



**B**
**7**

## DRAWING


**?**

## TERMINAL

**1**





Z	Y	X
0,75 ... 1,25	22,0 ±0,2 0	30,0 0 -0,1
1,25 ... 2,0	22,0 ±0,2 0	30,2 0 -0,1
2,0 ... 3,0	22,0 ±0,2 0	30,6 0 -0,2
3,0 ... 4,0	22,0 ±0,2 0	30,8 0 -0,2



?

## FUNCTION

1



?

## RATING

2

200 - 250 VAC  
T120 °C  
VDE 710

200 - 250 VAC  
T65 °C  
UL 496  
CSA C22.2

?

## BODY COLOR

1

black

X

?

custom

?

## LENS COLOR

ILLUMINATED ✨

G

red

H

orange

E

green

X

custom

?

0

0

0

0

0

0