



IN REPLY REFER TO:

United States Department of the Interior
BUREAU OF INDIAN AFFAIRS
EASTERN OKLAHOMA REGION
OSAGE AGENCY
POST OFFICE BOX 1539
PAWHUSKA, OKLAHOMA 74056-1539



MAY 10 2013

OPERATIONS REPORT FOR WEEK ENDING MAY 10, 2013

LOCATIONS:

9	NE 13-25-02	Senax, Inc. Arbuckle @ 2800' Elevation: 1020' G.L.	(McCord) Location: 270' FNL – 475' FEL
2-9H	NE 09-23-04	Horn Oil Company Mississippi @ 2500' Elevation: 835' G.L.	(Marsham) Location: 100' FSL – 1170' FEL
3-2	SW 02-25-08	Short Oil Company Mississippi Lime @ 2600' Elevation: 994' G.L.	(Meyers) Location: 990' FSL – 990' FWL
8	NE 03-25-08	Short Oil Company Mississippi Lime @ 2600' Elevation: 1068' G.L.	(Meyers) Location: 990' FSL – 990' FEL
7	NE 35-26-08	Short Oil Company Mississippi Lime @ 2600' Elevation: 968' G.L.	(Meyers) Location: 990' FSL – 990' FEL
8	SE 36-26-08	Short Oil Company Mississippi Lime @ 2600' Elevation: 967' G.L.	(Meyers) Location: 990' FSL – 330' FWL
9	SE 19-26-10	S M Oil & Gas Inc. Chat @ 2037' Elevation: 824' G. L.	(Johnson) Location: 630' FNL – 108' FEL
10	SE 19-26-10	S M Oil & Gas Inc. Chat @ 2048' Elevation: 835' G. L.	(Johnson) Location: 680' FNL – 790' FEL
11	SE 19-26-10	S M Oil & Gas Inc. Chat @ 2045' Elevation: 827' G. L.	(Johnson) Location: 688' FNL – 1255' FWL
12	SE 19-26-10	S M Oil & Gas Inc. Chat @ 2018' Elevation: 805' G. L.	(Johnson) Location: 890' FNL – 500' FWL

LOCATIONS CONTINUED:

13	SE 19-26-10	S M Oil & Gas Inc. Chat @ 2022' Elevation: 815' G.L.	(Johnson) Location: 1065' FSL – 500' FWL
----	-------------	--	---

LOCATION CORRECTION:

11-2W	NE 32-28-11	Performance Energy Resources <i>Correction of well # reported incorrectly. Reported Week Ending March 2, 2012.</i>
-------	-------------	---

30-1	SW 30-26-12	NTR Energy, LLC Location: 330' FSL – 1420' FWL <i>Correction of location, changed stake.</i>
------	-------------	--

COMPLETIONS:

13-27	NE 27-25-06	Sullivan and Company LLC TD @ 2822' Elevation: 1007' G.L.	Completion – Oil, Trace BOPD, 398 Gas, 2361 Water Location: 440' FNL – 2240' FEL
16	SE 27-25-06	Sullivan and Company LLC TD @ 2840' Elevation: 1006' G.L.	Completion – Oil, 85 Gas, 681 Water Location: 2095' FSL – 1740' FEL
15	NW 34-25-06	Sullivan and Company LLC TD @ 2918' Elevation: 1083' G.L.	Completion – Oil, 85 Gas, 681 Water Location: 663' FNL – 806' FWL
16	NE 34-25-06	Sullivan and Company LLC TD @ 2893' Elevation: 1122' G.L.	Completion – Oil, Skim Oil, 395 Gas, 861 Water Location: 575' FNL – 45' FEL
18	SW 35-25-06	Sullivan and Company LLC TD @ 3331' Elevation: 1099' G.L.	Completion – Oil, .7 Oil, 253 Gas, 742 Water Location: 545' FSL – 410' FWL
11-1W	NW 01-27-10	Performance Operating Co. TD @ 2300' Elevation: 940' G.L.	Completion – SWD Location: 330' FNL – 380' FEL
11-12	SE 14-25-11	Performance Operating Co. TD @ 2008' Elevation: 963' G.L.	Completion – Oil 5 Oil, Trace Gas, 200 Water Location: 330' FNL – 330' FWL
10-5	NE 08-21-12	Performance Operating Co. TD @ 1682' Elevation: 745' G.L.	Completion – Oil 5 Oil, 10 Gas, 120 Water Location: 990' FSL – 990' FEL

COMPLETIONS CONTINUED:

11-15	NW 09-25-12	Performance Operating Co. TD @ 1892' Elevation: 745' G.L.	Completion – Oil 5 Oil, Trace Gas, 150 Water Location: 990' FSL – 990' FEL
30-2	SE 30-26-12	NTR Energy, LLC TD @ 1102' Elevation: 820' G.L.	Completion – Dry TSTM Gas, 160 Water Location: 330' FSL – 660' FWL
30-1	SW 30-26-12	NTR Energy, LLC TD @ 1805' Elevation: 936' G.L.	Completion – Oil 3 Oil, TSTM Gas, 95 Water Location: 1420' FSL – 330' FWL

COMPLETION CORRECTION:

1318	SW 21-21-09	CEP Mid-Continent LLC	Location: 1750' FSL – 2380' FWL
------	-------------	-----------------------	---------------------------------


Correction of completion, location read incorrect. Reported Week Ending May 3, 2013.

CONVERSION:

13-7	NE 13-22-07	GKM Oil & Gas Elevation: 868' G. L.	SWD to Oil Location: 330' FNL – 1715' FEL
4	SE 01-23-09	Robinowitz Oil Company Elevation: 939' G. L.	Location: 990' FNL – 990' FWL
7	SE 29-23 09	Oklahoma Energy Elevation: 743' G. L.	Location: 990' FSL – 990' FWL

SUMMARY

11 COMPLETIONS
2 COMPLETION CORRECTIONS
11 LOCATIONS
1 LOCATION CORRECTION
3 CONVERSIONS
4 WORKOVERS

 5/10/13
ACTING Superintendent