

Vehicles with Problem:

2014-2016	GMC Sierra 1500
2014-2016	Chevrolet Silverado 1500
2015-2017	GMC Yukon
2015-2017	Chevrolet Suburban
2015-2017	Chevrolet Tahoe
2015-2017	Cadillac Escalade

Problem - Air Conditioning System Failure:

- Cracks in hoses, condensers and compressors
- Leaking refrigerant
- Losing pressure within the A/C system
- Fails to provide cooled air to cabin

Results in need to replace condenser, compressor and/or hoses, long waits for parts/repairs due to back-ordered parts, and no A/C in vehicle while waiting.
