




Photo Taken: 06/29/19



**Photo Taken: 06/30/19
Lost Apporx. 4ft In Height
By 15ft In Width In 24-
hours.**



**Photo Taken: 06/30/19
Lost Apporx. 4ft In Height
By 15ft In Width In 24-
hours.**



Erosion Threatens North Overpass



**Eroded Dunes In
Front Of Pool Deck
And South Overpass**